


OVERVIEW DRAWING



PARTS LIST

No.	Name	PCS
1	Ipad Holder	1
2	Screw	2
3	U-tube	1
4	Display sticker	1
5	Motor upper cover	1
6	Screw	5
7	Power cord	1
8	Motor holder	2
9	Screw	2
10	Motor	1
11	Belt	1
12	Power Switch	1
13	Motor under cover	1
14	Screw	2
15	Gas spring	2

No.	Name	PCS
16	Main frame	1
17	Screw	6
18	Floor pad	2
19	Screw	2
20	Rear cap R&L	2
21	Rear roller	1
22	Running board	1
23	Running belt	1
24	Side rail	2
25	Front roller	1
26	PCB	1
27	Nut	2
28	Wheel	2
29	Screw	2
30	Display screen	1